

Work Order ID 83973

83973

Page 1

April-30-12 2:37:41 PM

Item ID: D205-564-011

Accept

N900040100

Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Bearpaw

Start Date: 30/04/2012 Start Qty: 8.00

8

Cust Item ID:

Required Date: 14/05/2012 Req'd Qty: 8.00

8

Customer:

Reference:

Approvals:

Process Plan: MLJ

Date: 12/04/30

Tooling:

Date:

Run Start ***NR1***

QC:


Date:

SPC (Y/N):

Date:

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D2521	Rev J								
100		0.00							
100	DOCUMENT CONTROL								
DC		0.00							
Document Control	Memo								
	Photocopy blue file and type labels per PPP D205-564-011 CHG008								
151		0.00							
151	Pick Kit								
Packaging		0.00							
Packaging	Memo								
160		0.00							
160	QC4- 100% Inspect kits for completeness								
QC		0.00							
Quality Control	Memo								



W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 83973

83973

Page 2

April-30-12 2:37:41 PM

Item ID: D205-564-011

Accept

N900040100

Setup Start ***NS1***

Revision ID:

Item Name: Bearpaw

Stop ***NS2***

Start Date: 30/04/2012 Start Qty: 8.00 ***8***

Cust Item ID:

Required Date: 14/05/2012 Req'd Qty: 8.00 ***8***

Customer:

Reference:

Approvals: Process Plan: Date:

Tooling:

Date:

Run Start ***NR1***

QC: Date:

SPC (Y/N):

Date:

Stop ***NR2***

Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Tool ID

Tool #

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

170

Identify as per dwg & Stock Location

0.00

170

Packaging

Memo

0.00

Packaging

180

QC21- Final Inspection - Work Order Release

0.00

180

QC

Memo

0.00

Quality Control

Ex 12-7-13

12/7/11

mf 12-09-13

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

April-30-12 2:37:45 PM

Page 1

Work Order ID: 83973

83973

Parent Item: D205-564-011

D205-564-011

Parent Item Name: Bearpaw

Start Date: 30/04/2012

Required Date: 14/05/2012

Start Qty: 8.00

Required Qty: 8.00

Comments:

IPP F00.01.20 Changed pick list, MPP 2019, CHG006EC
 IPP Rev:G 06-08-28 As per Rev E JLM
 IPP Rev:H 08-01-11 Added Step #2 JLM Verified BY:EC
 IPP Rev:I 08-10-01 New Manufacturing Method JLM Verified By:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2521 *D2521* Bearpaw 205		Manufactured	No			151	Each	2.0000	2	16			
				<u>Location</u>				<u>Loc Qty</u>		<u>Loc Code</u>			
				ST495				2					
				75263				2					
D2182B055 *D2182B055* Clamp, Cushion Black 3.5" Long		Manufactured	No			151	Each	15.0000	8	64			
				<u>Location</u>				<u>Loc Qty</u>		<u>Loc Code</u>			
				ST402A				15					
				68746				7					
				73932				8					
D2274 *D2274* Radius Block		Manufactured	No			151	Each	632.0000	20	160			
				<u>Location</u>				<u>Loc Qty</u>		<u>Loc Code</u>			
				ST007				632					
				78233				22					
				81958				400					
				83258				210					

83973

JB

JB

12/07/13

83258

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

April-30-12 2:37:45 PM

Page 2

Work Order ID: 83973

83973

Parent Item: D205-564-011

D205-564-011

Parent Item Name: Bearpaw

Start Date: 30/04/2012

Required Date: 14/05/2012

Start Qty: 8.00

Required Qty: 8.00

D2529

Manufactured No

151 Each

483.0000

20

160

D2529

Washer

**

841435 JB



Location

Loc Qty

Loc Code

ST010

483

79485

18

81873

365

83544

100

D2947

Manufactured No

151 Each

48.0000

8

64

D2947

Clamp

**

85468 JB



Location

Loc Qty

Loc Code

ST456

48

73415

8

77557

40

D3544-041

Manufactured No

151 Each

5.0000

4

32

D3544-041

Clamp

**

20+83520 JB
12+85485

12/07/13



Location

Loc Qty

Loc Code

ST457

5

73301

4

77540

1

April-30-12 2:37:45 PM

Shop Packet Print

Page 2

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

April-30-12 2:37:45 PM

Page 3

Work Order ID: 83973

83973

Parent Item: D205-564-011

D205-564-011

Parent Item Name: Bearpaw

Start Date: 30/04/2012

Required Date: 14/05/2012

Start Qty: 8.00

Required Qty: 8.00

AN4-13A

Purchased

No

151

Each

953.0000



64

AN4-13A

Bolt

**

121652 JB

Location

Loc Qty

Loc Code

ST357

953

118838

8

119449

39

120187

19

120422

2

120770

400

121162

485

AN4-15A

Purchased

No

151

Each

539.0000



160

AN4-15A

Bolt

**

122141 JB

Location

Loc Qty

Loc Code

GA

100

120449

100

ST358

439

118706

3

119449

1

119749

19

120422

116

121444

100

121541

200

AN960JD416

NAS1149D0463J

Purchased

No

151

Each

30.0000



160

AN960JD416

Washer

**

121912 JB

12/07/13

Location

Loc Qty

Loc Code

ST351

30

116289

10

119097

20

April-30-12 2:37:45 PM

Shop Packet Print

Page 3

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

April-30-12 2:37:45 PM

Page 4

Work Order ID: 83973

83973

Parent Item: D205-564-011

D205-564-011

Parent Item Name: Bearpaw

Start Date: 30/04/2012

Required Date: 14/05/2012

Start Qty: 8.00

Required Qty: 8.00

MS21042L4

Purchased

No

151

Each

5,728.000



160

**

✓

JB

12/07/13

MS21042L4

Nut

S-80

Location

Loc Qty

Loc Code

ST300

5728

119075

728

121011

2000

121444

3000

121444

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

5.0 PARTS LIST

Qty	Part Number	Description
X	D205-564-011	BEARPAW INSTALLATION
8	D2182B055	RUBBER CUSHION
20	D2274	RADIUS BLOCK
2	D2521	BEARPAW
20	D2529	WASHER
8	D2947	CLAMP
4	D3544-041	CLAMP
8	AN4-13A	BOLT
20	AN4-15A	BOLT
20	AN960JD416	WASHERS
20	MS21042L4	NUT (OR MS21042-4)

Qty	Part Number	Description
X	DSI-9328-011	RUN-ON LANDING WEARPLATE KIT
2	D3511-041	WEARPLATE
16	AN4-17A	BOLT
4	AN4-11A	BOLT
4	AN970-4	WASHER
16	MS21042L4	NUT (OR MS21042-4)